

**National Transportation Safety Board
Washington, DC 20594**

Brief of Accident

Adopted 05/30/2003

DEN02FA034 File No. 13468	03/24/2002	Englewood, CO	Aircraft Reg No. N341DM	Time (Local): 16:31 MST		
Make/Model:	Cessna / 340			Fatal	Serious	Minor/None
Engine Make/Model:	Continental / TSIO-520-NB		Crew	1	0	0
Aircraft Damage:	Destroyed		Pass	3	0	0
Number of Engines:	2					
Operating Certificate(s):	None					
Type of Flight Operation:	Personal					
Reg. Flight Conducted Under:	Part 91: General Aviation					
Last Depart. Point: Gunnison, CO				Condition of Light: Day		
Destination: Same as Accident/Incident Location				Weather Info Src: Weather Observation Facility		
Airport Proximity: Off Airport/Airstrip				Basic Weather: Instrument Conditions		
				Lowest Ceiling: 1500 Ft. AGL, Overcast		
				Visibility: 5.00 SM		
				Wind Dir/Speed: 050 / 010 Kts		
				Temperature (°C): -2		
				Precip/Obscuration: Drizzle; Snow Shower / None		
Pilot-in-Command	Age: 63			Flight Time (Hours)		
Certificate(s)/Rating(s)				Total All Aircraft: 3563		
Airline Transport; Commercial; Multi-engine Land; Single-engine Land				Last 90 Days: Unk/Nr		
Instrument Ratings				Total Make/Model: 560		
Airplane				Total Instrument Time: UnK/Nr		

The pilot was flying a three leg IFR cross-country, and was on an ILS approach in IMC weather conditions for his final stop. Radar data indicated that the pilot had crossed the final approach fix inbound and was approximately 3 nm from the runway threshold when he transmitted that he had "lost an engine." Radar data indicates that the airplane turned left approximately 180 degrees, and radar contact was lost. A witness said "the airplane appeared to gain a slight amount of altitude before banking sharply to the left and nose diving into the ground just over the crest of the hill." Postimpact fuel consumption calculations suggest that there should have been 50 to 60 gallons of fuel onboard at the time of the accident. Displaced rubber O-ring seals on two Rulon seals in the left fuel valve and hydraulic pressure/deflection tests performed on an exemplar fuel valve suggest that the fuel selector valve was in the auxiliary position at the time of impact. The airplane's Owner's Manual states: "The fuel selector valve handles should be turned to LEFT MAIN for the left engine and RIGHT MAIN for the right engine, during takeoff, landing, and all emergency operations." No preimpact engine or airframe anomalies, which might have affected the airplane's performance, were identified.

Brief of Accident (Continued)

DEN02FA034				
File No. 13468	03/24/2002	Englewood, CO	Aircraft Reg No. N341DM	Time (Local): 16:31 MST

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL
Phase of Operation: APPROACH - FAF/OUTER MARKER TO THRESHOLD (IFR)

Findings

1. (C) PROCEDURES/DIRECTIVES - NOT FOLLOWED - PILOT IN COMMAND
 2. (F) FLUID,FUEL - STARVATION
 3. (F) 1 ENGINE
-

Occurrence #2: LOSS OF CONTROL - IN FLIGHT
Phase of Operation: APPROACH - FAF/OUTER MARKER TO THRESHOLD (IFR)

Findings

4. (F) AIRCRAFT CONTROL - NOT OBTAINED/MAINTAINED - PILOT IN COMMAND
 5. (F) STALL/SPIN - INADVERTENT - PILOT IN COMMAND
-

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: DESCENT - UNCONTROLLED

Findings

6. TERRAIN CONDITION - MOUNTAINOUS/HILLY

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.
the pilot not following procedures/directives (flying a landing approach with the left fuel selector in the auxiliary position).
Contributing factors were the loss of the left engine power due to fuel starvation, the pilot's failure to maintain aircraft control, and
the subsequent inadvertent stall into terrain.